

DATE 0015Z 15 SEP 62

~~SECRET~~

1	4
2	5
3	6

TO DIRECTOR

25X1A FROM [REDACTED]

ACTION: OPS (1-2-3-4-5)

INFO : S/C (6)

PRIORITY

TOR: 0114Z 15 SEP 62

IN: 48758

25X1A TO PRITY [REDACTED]

INFO [REDACTED]

25X1A

CITE

25X1A

054

25X1A [REDACTED] NIMBUS

25X1A REF: [REDACTED] 6502 (OUT 28303)

25X1A A. T-33 850 ARR [REDACTED] 14/2230Z WITH [REDACTED]

25X1A

B. PAR 3 REF MSG, DO NOT RECOMMEND CUTTING AND REWINDING
SINCE FACILITIES NOT AVAIL TO ACCOMP AND ALSO PRESENTS A
PROBELM OF PLACING BALLAST IN NOSE OF ARTICLE FOR PROPER CG.

TIME FOR PROCESSING SHOULD NOT BE EFFECTED UNDER PRESENT
PROCEDURES HOWEVER, SINCE ONLY EXPOSED PORTION OF [REDACTED]
PLUS A FEW FRAMES ON EACH END FOR PREFLIGHT ETC IS BEING SENT

25X1A

25X1A TO [REDACTED]

C. PAR 4 REF MSG, NORMAL PROCEDURES DO NOT REQUIRE TURNING
OFF AC GEN AND ELINT SYSTEMS. TURN OFF IS ACCOMP ONLY WHEN
ENG POWER IS REDUCED BELOW 80 PER CENT. DESCENT TO MAX RANGE
CRUISE IS NORMALLY ACCOMP AT 81 PER CENT WITH SUBJ EQUIP ON.
THE EARLY TURN OFF MSN 3089 WHICH WAS REFLECTED ON THE ROUGH
OVERLAY AND OCCURRED APPROX 5 MIN WEST OF 90 DEG WEST WAS
DUE TO POWER REDUCTION BELOW 80 PER CENT TO

GROUP I
EXCLUDED FROM AUTOMATIC
DOWNGRADING AND
DECLASSIFICATION

~~SECRET~~

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.

S E C R E T

25X1A [REDACTED] IN 48758)

PAGE TWO

CONSERVE ADDITIONAL FUEL. WE DO NOT ANTICIPATE THAT THIS WILL BE A COMMON OCCURRENCE. AT ANY TIME THIS EQUIP IS TURNED OFF AND/OR ON AGAIN, COMMENT:

25X1A WILL BE MADE IN THE [REDACTED] AND WILL BE REFLECTED ON THE OVERLAYS.

END OF MESSAGE

S E C R E T